



## INSTRUCTIONS FOR PART 45-1407 -DIGITAL THERMOMETER

**Note: Read instructions thoroughly before installing. Drilling required.**

1. Place bike on center stand.
2. Find a location for the thermometer.
3. Mark location for to drill a hole 1 ¼ x ¾ inch.
4. Using a small saw, finish cutting out rectangles.
5. Press clamp over meter from the back.
6. Install a red and black wire to the back of the thermometer with the Red going to the positive + and the Black going to the negative - .
7. Connect Red (positive) wire to battery and the Black wire to a ground.
8. Place temperature sensor in a place away from moving parts.



133 Gold St, Worcester, MA 01608 508-791-7552 800-821-9861 fax 508-793-2919 email: [info@addonaccessories.net](mailto:info@addonaccessories.net)